UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,906,428 B2

Page 1 of 1

DATED

: June 14, 2005 INVENTOR(S) : Rudolf Lehner

> It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10,

Line 50, should read as follows:

-- being disposed between said contact areas and above --.

Column 11,

Line 17, should read as follows:

-- surface, said buffer: --.

Line 47, should read as follows:

-- applying the buffer between the contact areas and above --.

Signed and Sealed this

Sixth Day of September, 2005

JON W. DUDAS

Director of the United States Patent and Trademark Office